



# Newing-Hall, Inc.

2019 Monroe Street . Toledo, Ohio 43604-1740

Phone:(419)255-8804 Fax:(419)255-6943

Phone:(800)255-8804 Fax:(800)435-7131

www.Newing-Hall.com sales@Newing-Hall.com

## Newing-Hall, Inc. EC/TLC Beep Code

S - Short tone L - Long tone

Beep Sequence	Error	Possible Causes
S-L-L-L	Memory error in motion buffer	Firmware execution error.
S-S-L-L	Character Data Bad	Bad font cartridge/chip(s)
L-L-S-L	Character backup onto bad font data	Firmware execution error
L-S-S-L	Font not available	Software error on job transmission, bad data in CHANGE text.
S-L-L-S	Writing data amid font block	Firmware execution error, bad address/memory on controller.
L-S-L-S	Line backup onto bad font data	Firmware execution error or bad font cartridge/chip.
S-S-L-S	Interrupt from local terminal	Ctrl-C from debug monitor
L-S-S-S	Memory overflow on font download	Software error on job transmission- controller RAM

Error Type	Red LED	Green LED	Beeper
ROM	ON	ON	Beep-2 Second
RAM	OFF	ON	Beep-5 Second
Timer	ON	OFF	Pulsing Beep
Math	OFF	OFF	Pulsing Beep