

EngraveLab


How to output pdf for proof without getting fills:

Create Elab file as usual

Select all items on your plate

Click on the Stroke and Fill tools icon on the left toolbar.

Now click the first icon, line style



This will open up the line style options at the top.


The one on the very left is no line, the middle is hairline, and the right is thick line. Select the hairline icon. Now you will need to put a transparent fill on the items.

Select the line/fill icon on the lower palette, it looks like a / with a square under it, it is the second icon to the right of the arrow keys at the bottom, to the left of the colors.

Then you will need to left click on the invisible fill icon just to the right of the line/fill icon that is white with hash marks thru it.

Now when you output this file as pdf it will not fill in the centers.

Line style →



Invisible fill →