

Knowledge Base: KB1025 - Table Packing Instructions

November 15, 2005

Dear Customer,

Please return flatbed table as shown below to avoid shipping damages. **CUSTOMERS WILL BE RESPONSIBLE FOR TABLES DAMAGED DUE TO INCOMPLETE OR IMPROPER PACKING.**

1. Move the bridge (4) to the rear of the table until it touches the rear cross-member (5).
2. Insert Styrofoam Bridge block (2) beneath bridge as shown. Bridge block (2) should fit very snug between bridge (4) & center cross-member (1).
3. Use two large cable ties (3) to the bridge & center cross-member (1) together. Run large cable ties (3) under center cross-member (1) & up between rear cross-member (5) & center cross-member (1). Make sure large cable ties (3) are very tight.

Note: Cables ties should NOT wrap around rear cross-member.

4. All tables must be returned with factory authorized cartons & inserts.
See figure 2.

CALL CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS OR NEED PACKING MATERIALS.




Figure 1



Figure 2

IMPORTANT:

Figure 2 does not show the remaining packing foam or boxes used at the time of packing prior to shipping. It is necessary to include the packing foam and the empty controller box to insure the table is properly secured. Failure to pack the table with the controller box and packing foam will result in damaged equipment during shipping.

CALL CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS OR NEED PACKING MATERIALS.